

www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1132

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1132 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1132 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1133

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1133
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1133 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1134

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1134
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1134 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1135

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1135 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1135 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1136

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1136 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1136 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1137

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1137 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1137 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1138

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1138
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1138 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

NT Perkins BAppSC(AppGeol) BEng(Hons1) RPEQ
MV Geale BEng(Civil) MBA CPEng MIE Aust RPEQ
GEJ Grav

BE(Civil) MIE Aust RPEQ

P Elkington

Associates
CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1139

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1139
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1139 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1140

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1140
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1140 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurvevs.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1141

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1141
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1141 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors PJ Dixon

BE(Hons) RPEQ

NT Perkins BAppSC(AppGeol) BEng(Hons1) RPEQ MV Geale BEng(Civil) MBA CPEng MIE Aust RPEQ

GEJ Gray
P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1142

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1142 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1142 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ

BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1143

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1143
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1143 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1144

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1144
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1144 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

son BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1145

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1145 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1145 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1146

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1146 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1146 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1147

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1147
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1147 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1148

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1148
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1148 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1149

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1149
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1149 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1150

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1150 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1150 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1151

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1151 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1151 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1152

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1152 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1152 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1153

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1153
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1153 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ

BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1154

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1154
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1154 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1155

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1155 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1155 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1156

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1156 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1156 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1157

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1157 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1157 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

nson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1158

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1158
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1158 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1159

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1159
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1159 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1160

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1160 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1160 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED

