


Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 731





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".


Shin To Amiri

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering)

B.Eng. (Civil Engineering) <a href="mailto:shina@ausgeotest.com.au">shina@ausgeotest.com.au</a> Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 732





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".


Shin To Amiri

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 733





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".


Shin To Amiri

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 734





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".


Shin To Amiri

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering)

B.Eng. (Civil Engineering) <a href="mailto:shina@ausgeotest.com.au">shina@ausgeotest.com.au</a> Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 735





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".

Muly




Shin To Amiri Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 736





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".

ENGINEERS

Shin To Amiri

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering)

B.Eng. (Civil Engineering) <a href="mailto:shina@ausgeotest.com.au">shina@ausgeotest.com.au</a>

Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 - Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 737





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".

ENGINEERS AUSTRALIA

Shin To Amiri Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 738





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".




Shin To Amiri Senior Geotechnical Engineer MIE Aust (EA ID: 6820691) Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 739





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".

Still



Shin To Amiri Senior Geotechnic

Senior Geotechnical Engineer MIE Aust (EA ID: 6820691)

Ph.D. (Geotechnical Engineering),


M.Eng. (Geotechnical Engineering) B.Eng. (Civil Engineering)

shina@ausgeotest.com.au

Mob: 0448597976



Certificate of Controlled Filling
Earthworks Operations (AS3798 – Level 1 Inspection & Testing)
AGTE240310, William Lakes Stage 7
Lot 740





Level 1 Site Area

The filling in the areas as defined above and in the Level 1 Report pertaining to the above mentioned project meets the requirements for "structural fill for residential applications" in accordance with AS3798. The fill has been placed, compacted and tested in accordance with AS3798 and the fill meets the requirements for controlled fill in accordance with AS2870 (2011) "Residential Slabs and Footings".

\_\_\_\_

ENGINEERS AUSTRALIA

Shin To Amiri Senior Geotechnical Engineer MIE Aust (EA ID: 6820691)

Ph.D. (Geotechnical Engineering), M.Eng. (Geotechnical Engineering)

B.Eng. (Civil Engineering) <a href="mailto:shina@ausgeotest.com.au">shina@ausgeotest.com.au</a> Mob: 0448597976