

www.soilsurveys.com.au

Directors PJ Dixon

BE(Hons) RPEQ

NT Perkins BAppSC(AppGeol) BEng(Hons1) RPEQ MV Geale BEng(Civil) MBA CPEng MIE Aust RPEQ

GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling Lot 1161

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1161
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1161 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined on the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.


Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1162

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1162 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1162 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1163

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1163
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1163 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

on BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1164

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1164
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1164 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

n BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1165

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1165
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1165 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1166

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1166
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1166 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurvevs.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ

BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1167

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1167
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1167 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1168

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1168
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1168 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1169

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1169
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1169 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1170

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1170 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1170 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1171

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1171
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1171 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

ohnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1172

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1172
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1172 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1173

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1173
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1173 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1174

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1174
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1174 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors PJ Dixon

BE(Hons) RPEQ

NT Perkins BAppSC(AppGeol) BEng(Hons1) RPEQ MV Geale BEng(Civil) MBA CPEng MIE Aust RPEQ

GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1175

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1175
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1175 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1176

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1176
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1176 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurvevs.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

on BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1177

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1177
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1177 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1178

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1178
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1178 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ
BAppSC(AppGeol) BEng(

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1179

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1179
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1179 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins
MV Geale

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

GEJ Gray
P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1180

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1180 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1180 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ

BE(Civil) MIE Aust RPEQ

MV Geale BEng(Civil) MBA CPEng MIE Aust RPEQ
GEJ Grav

Associates

P Elkington

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1181

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1181 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1181 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1182

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1182
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1182 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurvevs.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1183

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1183
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1183 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1184

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1184
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1184 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates CP Johnson

son BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1185

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1185 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1185 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors PJ Dixon

BE(Hons) RPEQ

NT Perkins MV Geale GEJ Gray P Elkington BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1186

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1186
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1186 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors PJ Dixon

BE(Hons) RPEQ

NT Perkins MV Geale GEJ Gray BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

P Elkington BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1187

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1187 THE SURROUNDS – STAGE ONE – 1A - 1F CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1187 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

n BE(Civil) MIE Aust RPEQ

Associates CP Johnson

BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1188

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1188
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1188 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED





www.soilsurveys.com.au

Directors
PJ Dixon
NT Perkins

BE(Hons) RPEQ

BAppSC(AppGeol) BEng(Hons1) RPEQ BEng(Civil) MBA CPEng MIE Aust RPEQ

MV Geale GEJ Gray P Elkington

BE(Civil) MIE Aust RPEQ

Associates

CP Johnson BEng(Civil) RPEQ

Gold Coast Office

Job No: 214-11753

Ref: Certificate Of Controlled Filling - Lot 1189

Author: Curtis Skinner

16th December, 2016

Villawood Developments Country Club Drive Helensvale QLD 4212

Email: michaelw@villawoodproperties.com

RE: CERTIFICATE OF CONTROLLED FILLING – LOT 1189
THE SURROUNDS – STAGE ONE – 1A - 1F
CERTIFICATION OF EARTHWORKS

Fill was placed on this lot during the construction of this estate.

Soil Surveys Engineering Pty Ltd was commissioned on this project to provide earthworks inspection and testing services on a Level 1 basis as detailed in clause 8.2 of AS 3798-2007 "Guidelines on earthworks for commercial and residential developments". Full details of the inspection and testing program are provided in the Soil Surveys Engineering report (ref 2-11753, 2016-10-28, BR VER 1).

Soils Surveys Engineering Pty Limited certify that the fill placed in Lot 1189 of The Surrounds – Stage One – as shown on all attached plans, has been carried out in a responsible manner and in accordance with table 5.1.1 AS 3798 and the project specifications.

All fill in the areas defined in the attached lot location plan, within the time frame of our inspection and testing programme between 16/05/2016 and 24/06/2016 (excluding topsoil placed subsequent to completion of controlled filling) is considered to be "controlled fill" in accordance with AS 2870 "Residential Slabs and Footings" (Clause 6.4.2 (a)) and AS 3798.

Unless otherwise stated, Level 1 certification does not address any other geotechnical issues which may be relevant to building construction and serviceability.

C SKINNER

P.J DIXON (RPEQ 4150)

for and on behalf of

SOIL SURVEYS ENGINEERING PTY LIMITED

